

Keith Baldinger Town of Shrewsbury Public Buildings Division Manager 100 Maple Ave Shrewsbury, MA 01545

RE: Shrewsbury High School - 64 Holden Street

August 26, 2020

AALANCO Service Corporation at your request has performed an HVAC assessment at Shrewsbury High School. Assessment is as follows:

AIR FILTERS

- Ensured that clean, correct filters are in place
- Confirmed proper fit of filters to prevent air from bypassing (flowing around) the air filter
- Confirmed proper installation of filters (correct direction for airflow)

DRAIN PANS

- Ensured that drain pans pitch toward the drain (to prevent water from accumulating)
- · Checked drain pans for mold and mildew
- Cleaned drain pans

COILS

• Ensured that heating and cooling coils are clean

ROOFTOP UNITS & INDOOR AIR HANDLING UNITS #1 - #21

- Ensured that the interior of air-handling unis (air-mixing chamber & fan blades) are clean
- Ensured that ducts are clean.

Exhaust Fans #1 - #81

- Ensure proper operation of motors, & fan speeds
- Ensure all belts, sheaves, & pulleys are aligned & operating correctly

CONTROLS FOR OUTDOOR AIR SUPPLY

- Ensured that all air dampers open to maximum position
- Ensured that minimum position provides adequate outdoor air for occupants

CONTROLS INFORMATION

Obtained and reviewed all design inside/outside temperature and humidity requirements, controls specifications, as-built mechanical drawings, and confirm building control system for proper operation.

Sincerely, Joel Darby Account Rep / Project Manager Aalanco Service Corporation

AALANCO SERVICE CORPORATION

80-B Turnpike Road • Westborough MA 01581 • (508) 366-1449 • (800) 215-6698 • Fax (508) 366-1196