

Keith Baldinger Town of Shrewsbury Public Buildings Division Manager 100 Maple Ave Shrewsbury, MA 01545

RE: Parker Road Preschool - 15 Parker Rd

August 28, 2020

AALANCO Service Corporation at your request has performed an HVAC assessment at Parker Road Preschool. Assessment is as follows:

York ROOFTOP UNITS #1 - #6 for the classrooms in the newer addition

- All filters are clean & properly installed
- Ensured proper operation of the factory installed economizers (unit controlled)
- Units #2 & #5 need economizer motor actuators repairs in process
- · Cooling coils & condensate drains are clean & mold free
- Gas heat exchangers are in good working order

Trane Rooftop unit for rooms 7,8,9, & the Nurse

- Filters are clean & properly installed
- Unit is in good working order with proper economizer controls
- Cooling coil & condensate drain are clean & mold free
- · Gas heat exchanger is in good working order

York Rooftop unit for SPED & Help desk area

- Filters are clean & properly installed
- Unit is in good working order with proper economizer controls
- Cooling coil & condensate drain are clean & mold free
- Gas heat exchanger is in good working order

Trane Rooftop unit for Preschool offices

- Filters are clean & properly installed
- There is no outdoor air economizer on this unit factory economizer is available for this unit
- Cooling coil & condensate drain are clean & mold free
- Gas heat exchanger is in good working order

Building control system

- The Building control system at Parker is basically for monitoring purposes only
- Fresh air is controlled by the individual unit mounted controls

Sincerely, Joel Darby Account Rep / Project Manager AALANCO Service Corporation

AALANCO SERVICE CORPORATION

80-B Turnpike Road • Westborough MA 01581 • (508) 366-1449 • (800) 215-6698 • Fax (508) 366-1196

GAS/OIL BURNER SERVICE • MECHANICAL SERVICES • PLANNED MAINTENANCE PROGRAMS •AIR CONDITIONING SERVICE • BOILERS & BURNERS • TANK INSTALLATION/REMOVAL/TESTING • MOBILE BOILERS