
Summer 2016 School Facility Capital Repairs and Improvements

September 14, 2016

S.H.S. Indoor Track – Crack Repair



S.H.S. Gym Floor Re-Finish




S.H.S. Basketball Courts: During	
	1
S.H.S. Basketball Courts: After	
	1
S.H.S. Tennis Courts: During	

S.H.S. Tennis Courts: After





Coolidge School Paving





Paton: Boiler Room Equipment





Paton: Café & Finished Classroom





Paton: Classroom & New Water Heater





Spring Street:				
New Gas Line Installation				





Spring Street: Gas Line on Driveway





Spring Street: Gym and Lobby





Spring Street: Roof Decking & New HVAC Units for Modular Classrooms





Spring Street: First Floor Classroom



Spring Street: Second Floor Classrooms





Spring Street: Bathroom and Cafeteria





•	•	•	•	